DEFAR		DC05 M13501 HAND HUMAN SERVICES SAMEDICAID SERVICES	45	423 (20 300) F 44749 PRINTED: 10/20/20 FORM APPROVE OMB NO. 0938-03				
STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:			(X2) MU A. BUILI		CONSTRUCTION 01 - BUILDING #1	(X3) DATE S	SURVEY	
		445141	B. WING	<u> </u>		10/	18/2011	
NAME OF PROVIDER OR SUPPLIER BRADLEY HEALTH CARE & REHAB				TREET ADDRESS, CITY, STATE, ZIP CODE 2910 PEERLESS RD CLEVELAND, TN 37312				
(X4) ID PREFIX TAG	(EACH DEFICIENCY	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	PREFIX TAG		PROVIDER'S PLAN OF CO (EACH CORRECTIVE ACTION CROSS-REFERENCED TO THE DEFICIENCY)	SHOULD BE	(X5) COMPLETION DATE	
q=zz	Required automatic continuously mainta condition and are in periodically. 19.7 25, 9.7.5 This STANDARD is Based on observation on Octrevealed 6 of 26 sp was not quick responsible revealed wiring attasprinkler system abdoors on 400 hall. Observation on Octrevealed wiring attasprinkler system abdoors on 400 hall. Observation on Octrevealed wiring attasprinkler system abdoors on 400 hall. NFPA 101 LIFE SA Heating, ventilating with the provisions in accordance with	tober 18, 2011 at 8:45 a.m., rinkler heads in the kitchen onse heads. tober 18, 2011 at 9:40 a.m., iched to the automatic rove the ceiling at the fire rove the ceiling at patient room ove the ceiling at patient room ove the ceiling at patient room and air conditioning comply of section 9.2 and are installed	K 06	B. C.	affected by the deficiency if r	eplaced with compliance 9.7.5. To the ove the emoved as stem is free are not to the even the form the 100 11. The y wire eved, all to be not corrected, d and the current esprinkler ing that is not	11/09/11	
LABORATOR	P DIRECTOR'S OR PROVID	DER/SUPPLIER REPRESENTATIVE'S SIGN	ATURE		TITLE		(X8) DATE	

M13501

DC05

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

FORM CMS-2567(02-99) Previous Versions Obsolete

Evant ID: PBF221

Facility ID: TN0601

If continuation sheet Page 1 of 3

8652125642 > 423 728 5889 P 44/49

UUJE IEJUME /

463 160 JOOF F 43/47

PRINTED: 10/20/2011 FORM APPROVED

CENTERS FOR MEDICARE & MEDICAID SERVICES OMB NO. 0938-0391 STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY COMPLETED IDENTIFICATION NUMBER: A. BUILDING O1 - BUILDING #1 B, WING 445141 10/18/2011

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

BRADLEY HEALTH CARE & REHAB			2910 PEERLESS RD CLEVELAND, TN 37312			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (75)			
K 067	Continued From page 1	K 067	37			
l/ 4.4=	This STANDARD is not met as evidenced by: Based on observation, record review and interview the facility failed to assure the HVAC unit is maintained in accordance with the manufactures recommendations. The findings include: Observation, record review and interview with maintenance director on October 18, 2011 at 11:15 a.m. confirmed the facility failed to perform the 4-year required maintenance to the fire dampers. Based on observation, the facility failed to assure the HVAC system is maintained to ensure the safety of the staff and residents. The findings include: Observation on October 18, 2011 at 8:30 a.m. revealed no positive air flow installed in Café clean storage closet located outside the kitchen area.		A. We are in the process of servicing the fire dampers on the HVAC system to bring them into full compliance with NFPA 19.5.2.1 and NFPA 19A 19.5.2.2. On a go-forward basis the 4 year required maintenance of the fire dampers will be completed as appropriate. The café clean storage closet outside of the kitchen area has had a vent installed to provide for positive air flow to the closet (10/31/11). B. All residents have the potential to be affected by the deficiency if not corrected. C. All HVAC systems in the facility will be operated in accordance with current applicable NFPA codes and regulations. Positive air flow in required closet spaces and other areas will be maintained in full adherence to all applicable current codes. D. Environmental Services Director will monitor for compliance.			
\$3∞D	NFPA 101 LIFE SAFETY CODE STANDARD Electrical wiring and equipment is in accordance with NFPA 70, National Electrical Code. 9.1.2	K 147				
! !	This STANDARD is not met as evidenced by: Based on observation, the facility falled to assure electrical wiring is installed in accordance with NFPA 70.					
	The findings include:					

FORM CMS-2567(02-99) Pravious Vorsions-Obsolete

Event ID: P8F221

Facility ID: TN0501

If continuation sheet Page 2 of 3

ORM CMS-2567(02-99) Previous Verglons Obsolute

Event ID: PBF221

Facility ID: TN0601

If continuation sheet Page 3 of 3